

**BEST AVAILABLE COPY**

FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 8

This exploded perspective view shows the assembly of the mechanical components. Part 6 is a bracket with a central hole. Part 11 is a U-shaped bracket that fits into the central hole of part 6. Part 12 is a long shaft with a threaded end. Part 13 is a conical bush that fits onto the threaded end of part 12. Part 13a is a smaller conical bush that fits onto the other end of part 12. Part 14 is a hook-shaped component that fits into the end of part 12. Part 15 is a small cylindrical component that fits into the end of part 12.

FIG. 9




FIG. 10




FIG. 11






FIG. 12




FIG. 13






FIG.15





FIG. 15



**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

**BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

☐ BLACK BORDERS

☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES

☐ FADED TEXT OR DRAWING

☒ BLURRED OR ILLEGIBLE TEXT OR DRAWING

☐ SKEWED/SLANTED IMAGES

☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS

☐ GRAY SCALE DOCUMENTS

☐ LINES OR MARKS ON ORIGINAL DOCUMENT

☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

☐ OTHER: \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**